

MERIT PROPERTY INSPECTIONS

(813)485-4335 info@meritinspects.com https://meritinspects.com/



PROPERTY INSPECTION REPORT


1234 Main St Tampa, FL 33607

Buyer Name 06/30/2025



Inspector
Abby Bullock

Professional Home Inspector
(813)485-4335
info@meritinspects.com



Agent **Buyer Agent**

TABLE OF CONTENTS

1: Information	5
2: I. Structural Systems	8
3: II. Electrical Systems	23
4: III. Heating, Ventilation and Air Conditioning Systems	26
5: IV. Plumbing Systems	31
6: V. Appliances	36
7: VII. Broad Limitations & Closeout	40

Merit Property Inspections Page 2 of 40

SUMMARY







2.1.1 I. Structural Systems - A. Foundations: Slab - foundation cracks - minor

2.1.2 I. Structural Systems - A. Foundations: Slab - foundation cracks - major

2.1.3 I. Structural Systems - A. Foundations: Trees near structure

2.2.1 I. Structural Systems - B. Grading and Drainage: Gutters are full

2.2.2 I. Structural Systems - B. Grading and Drainage: Gutter is crushed

2.2.3 I. Structural Systems - B. Grading and Drainage: Gutter missing splashblock

2.2.4 I. Structural Systems - B. Grading and Drainage: Low clearance to grade

2.2.5 I. Structural Systems - B. Grading and Drainage: No grading (flat) slope

2.3.1 I. Structural Systems - C. Roof Covering Materials: Re-caulking needed

2.4.1 I. Structural Systems - D. Roof Structures and Attics: Insulation is unevenly distributed

🔼 2.4.2 I. Structural Systems - D. Roof Structures and Attics: Attic ladder damaged

2.5.1 I. Structural Systems - E. Walls (Interior and Exterior): Caulking deteriorated and/or missing

2.5.2 I. Structural Systems - E. Walls (Interior and Exterior): Cracks major

2.5.3 I. Structural Systems - E. Walls (Interior and Exterior): Cracks minor

2.5.4 I. Structural Systems - E. Walls (Interior and Exterior): Cabinet - rotting cabinetry

2.5.5 I. Structural Systems - E. Walls (Interior and Exterior): Thermal - hot/cold spot showing in thermal scan

2.5.6 I. Structural Systems - E. Walls (Interior and Exterior): Vegetation rubbing against siding

2.6.1 I. Structural Systems - F. Ceilings and Floors: Ceiling - sheetrock cracks minor

2.6.2 I. Structural Systems - F. Ceilings and Floors: Flooring - tiles loose / cracked or missing

2.6.3 I. Structural Systems - F. Ceilings and Floors: Flooring - carpet wrinkling present

2.6.4 I. Structural Systems - F. Ceilings and Floors: Ceiling- exposed nail heads on sheetrock (nail pop)

2.7.1 I. Structural Systems - G. Doors (Interior and Exterior): Door rubs / sticks and is misaligned

2.9.1 I. Structural Systems - H. Windows: Single pane windows (entire property)

2.9.2 I. Structural Systems - H. Windows: Windows should be recaulked (entire property)

2.9.3 I. Structural Systems - H. Windows: Window screen is damaged

Merit Property Inspections Page 3 of 40

- 2.11.1 I. Structural Systems K. Porches, Balconies, Decks, and Carports: Old concrete porch cracks, separation, or heaving
- 3.2.1 II. Electrical Systems B. Branch Circuits, Connected Devices, and Fixtures: Fixture damaged bulb cover
- 3.2.2 II. Electrical Systems B. Branch Circuits, Connected Devices, and Fixtures: Outlet GFCI not functioning
- 3.2.3 II. Electrical Systems B. Branch Circuits, Connected Devices, and Fixtures:
- 4.2.1 III. Heating, Ventilation and Air Conditioning Systems B. Cooling Equipment: Condenser freon insulation missing or damaged
- 4.2.2 III. Heating, Ventilation and Air Conditioning Systems B. Cooling Equipment: Condenser vegetation is too close
- 4.2.3 III. Heating, Ventilation and Air Conditioning Systems B. Cooling Equipment: Evaporator- Freon leak
- 4.3.1 III. Heating, Ventilation and Air Conditioning Systems C. Duct Systems, Chases, and Vents: Duct cleaning is recommended
- 5.1.1 IV. Plumbing Systems A. Plumbing Supply, Distribution Systems, and Fixtures: Fixture dripping
- ⊙ 5.1.2 IV. Plumbing Systems A. Plumbing Supply, Distribution Systems, and Fixtures: Toilet is loose
- 5.3.1 IV. Plumbing Systems C. Water Heating Equipment: Water heater sitting on the ground
- 5.3.2 IV. Plumbing Systems C. Water Heating Equipment: Water heater near or past expected service lifespan
- 6.6.1 V. Appliances F. Mechanical Exhaust Vents and Bathroom Heaters: Vent fan is noisy

Merit Property Inspections Page 4 of 40

1: INFORMATION

		IN	NI	NP	D
1.1	Rodent & Pest Control	Χ			

IN = Inspected

NI = Not Inspected

NP = Not Present

D = Deficiency

Information

Date of inspection

06/30/2025

Photo Captions:

This inspection will use photo captions that indicate locations such as right, left, front, and back. These directions refer to how a person standing at the front of the property looking at it would see it. For example, the "front left bedroom" would be located on the front left side of the structure, as person would reference if standing at the front of the property looking at the structure.

How to Use This Report:

Your inspection is divided into four (4) basic categories of inspection:

- 1. *Inspected (I)* Item or category was inspected. Comments and photos may be provided by the inspector that shows proof of functionality and/or documentation of existence.
- 2. Not Inspected (NI) Inspector found this item present but did not inspect it.
- 3. Not Present (NP) Inspector was not able to locate this item for inspection.
- 4. *Deficient (D)* Inspector will check this if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by State standards of practice (as applicable). General deficiencies include inoperability, material distress, water penetration, damage, and deterioration, missing components, and unsuitable installation.

Type of building Single Family Attached	Style Traditional	In attendance Buyer Agent
Weather conditions Clear	Outdoor temperature 80°F to 90°F	Occupancy & furnishings Vacant, Semi-Furnished
Inspection address 1234 Main St, Tampa, FL 33607	Inspection company Merit Property Inspections	Client's name Buyer Name
Agent's name	Inspector's name	Year built

Abby Bullock

Square feet

Buyer Agent

2449

2006

Thermal / infrared scan completed

This inspection included thermal imagery as part of your inspection package.

An infrared camera is a tool used during a home inspection to find hidden problems that can't be seen with the naked eye. The camera detects heat differences in walls, ceilings, and floors, which can reveal issues like water leaks, missing insulation, electrical hot spots, or air leaks.

Photos in this section, if they are present, may not represent a deficiency and are primarily for documentation purposes of inspection. Deficiencies from thermal imagery can also be documented below and/or throughout the report as discovered.



Limitations

General

FURNISHINGS OBSTRUCTION

The property contains furnishings. Furnishings can obstruct the inspectors view and access to particular areas of the home. As such, the inspector performed the inspection to the best of their abilities. Due to liability considerations, the inspector is not permitted to move furnishings to complete an inspection.

General

RECENT REMODELING

Merit Property Inspections Page 6 of 40

The structure appears to have been recently painted, skim-coated, touched-up, floored, tiled, and/or undergone other "remodeling" activities. This can obscure visual deficiencies such as cracks, mold, stains, and other defects. The inspector always makes a thorough effort to search for defects in accessible areas, but will not find problems hidden by fresh paint, caulk, trim, tile, cabinets, flooring, etc.

Merit Property Inspections Page 7 of 40

2: I. STRUCTURAL SYSTEMS

		IN	NI	NP	D
2.1	A. Foundations	Χ			Χ
2.2	B. Grading and Drainage	Χ			Χ
2.3	C. Roof Covering Materials	Χ			Χ
2.4	D. Roof Structures and Attics	Χ			Χ
2.5	E. Walls (Interior and Exterior)	Χ			Χ
2.6	F. Ceilings and Floors	Χ			Χ
2.7	G. Doors (Interior and Exterior)	Χ			Χ
2.8	J. Fireplaces and Chimneys			Χ	
2.9	H. Windows	Χ			Χ
2.10	I. Stairways (Interior and Exterior)			Х	
2.11	K. Porches, Balconies, Decks, and Carports	Χ			Χ
2.12	L. Other	Χ			

IN = Inspected NI = Not Inspected NP = Not Present D = Deficiency

Information

A. Foundations: Type of

foundation

Slab on Grade

A. Foundations: Performance - work may be needed

The foundation exhibited enough indications of possible foundation issues to warrant the opinion from the inspector that a deeper dive may be necessary. Foundation shifting has caused (some or all):

- Visible foundation cracks
- · Exterior siding cracking
- Interior sheetrock cracking/separation
- Door misalignment
- Windows that won't open
- Unevenness in the walk of the structure

It is recommended that an engineering foundation evaluation be performed to ensure elevation, deflection, tilt is computed and analyzed to the Foundation Performance Association (FPA) standards. Inspector is not an Engineer, so engineering level of performance and repair recommendations are limited.

Client should talk with the owner about previous foundation repairs and ensure warranty paperwork exists for any repairs that may have already been completed. Warranty paperwork in most cases requires transfer paperwork and a fee. Also, an elevation plot (if not part of this inspection) is recommended to determine exact elevation discrepancies throughout the foundation and to document the problems for measurements in the future.

Merit Property Inspections Page 8 of 40

C. Roof Covering Materials: Roof covering material (w/ photos)

Asphalt / Composition Shingles



C. Roof Covering Materials: Inspected roof from Roof, Ground, Ladder

C. Roof Covering Materials: Roof overall condition

New/Excellent

Merit Property Inspections Page 9 of 40

D. Roof Structures and Attics: Inspected attic from

Limited Attic Walk



D. Roof Structures and Attics: Type of insulation (w/ photos)

Blown-In / Loose Fill



Merit Property Inspections Page 10 of 40

D. Roof Structures and Attics: Approximate depth of insulation

11.5 Inches (R-38) (2x12)

This is considered to represent the approximate average depth and type of insulation discovered during this inspection.



Attic

D. Roof Structures and Attics: Type of underlayment

Plywood



E. Walls (Interior and Exterior): Wall material (exterior)
Stucco



Merit Property Inspections Page 11 of 40

E. Walls (Interior and Exterior):

Wall material (interior)
Drywall

Limitations

A. Foundations

PARTS OF THE FOUNDATION ARE NOT VISIBLE

Some areas of the foundation are not visible. This may be due to overgrowth, natural ground being builtup too high, or stucco extending down to the soil grade. In these areas, the inspector is not able to evaluate the foundation from the exterior and is limited to walking the interior for visible foundation problems.

A. Foundations

PARGE COAT PRESENT

There are exposed areas of the foundation that are covered with a parge, a cementitious mortar on the perimeter foundation wall. The purpose of parge is to provide a cosmetic overlay and seal the slab from moisture/insect infiltration. Parge can also cover defects, as such, it's presence does limit the inspector's ability to visually evaluate the foundation in these areas.

D. Roof Structures and Attics

LIMITED ATTIC ACCESS

Attic space is limited due to obstructions from framing supports, plenums and/or duct-work that is installed, or insulation that hides supports used to safely traverse the attic space and do a complete inspection.

E. Walls (Interior and Exterior)

STUCCO INSPECTION RECOMMENDATION

Stucco siding can be one of the most costly and problematic siding choices, particularly in geographic areas with high levels of temperature, humidity and rainfall. Moisture intrusion through stucco defects on a wood frame structure can lead to rot of the framing structure and have negative effects on the indoor air quality (mildew/mold). A great amount of detail and skill is required during the installation of stucco veneer to achieve proper performance.

Due to the severity of stucco-related issues (when they exist), it is always recommended that a standalone stucco inspection is performed by a specialty company when a large amount of the structure's exterior is stucco. Specialty stucco inspectors can perform detailed inspections using special devices/tools that will provide the client more information on stucco types, risk, common issues, and costs.

Observations

2.1.1 A. Foundations

SLAB - FOUNDATION CRACKS - MINOR



Merit Property Inspections Page 12 of 40

Minor cracking was noted at the foundation. This is common as concrete ages and shrinkage surface cracks are normal. Recommend patching the minor cracks to prevent moisture/pest intrusion. Also recommend monitoring for more serious shifting/displacement.

Recommendation

Recommend monitoring.



Garage

2.1.2 A. Foundations

SLAB - FOUNDATION CRACKS - MAJOR



Severe cracking noted at the foundation. This is typically consistent with soil movement and could lead to serious damage to structural components, foundation and/or slabs. It is possible that this crack has already contributed to structural deficiencies.

Recommend a foundation contractor evaluate and provide a cost/report on course of action and remedy.

Recommendation

Contact a foundation contractor.







Garage Garage

Garage

2.1.3 A. Foundations

TREES NEAR STRUCTURE



Trees growing near the structure may effect future performance of the foundation. Evaluate, remove, monitor, and/or address as necessary.

Recommendation

Recommended DIY Project



Front Right

2.2.1 B. Grading and Drainage

GUTTERS ARE FULL



Merit Property Inspections Page 13 of 40

The gutters are full of leaves and debris. Recommend removal for functional use of gutters.

Recommendation

Contact a handyman or DIY project



Back

2.2.2 B. Grading and Drainage

Recommendation

GUTTER IS CRUSHED

A downspout gutter is crushed. This can cause flow restrictions and debris buildup in the gutter system that could lead to an overflow. Recommend replacing the crushed portion of the gutter as necessary.

Recommendation

Contact a handyman or DIY project





Across structure

2.2.3 B. Grading and Drainage

Recommendation

GUTTER MISSING SPLASHBLOCK

Some or all of the gutter downspouts are missing splash blocks. Splash blocks help disperse the water away from the foundation and prevent the erosion of soils. Recommend installing splash blocks at all necessary locations.

Recommendation

Contact a handyman or DIY project



Across structure

2.2.4 B. Grading and Drainage

LOW CLEARANCE TO GRADE



Merit Property Inspections Page 14 of 40

The clearance from the finished floor elevation (i.e. top of slab) to the exterior grade (i.e. ground) should be 6-inches or greater. This will prevent pooling surface water runoff from storm events from entering the structure. Recommend re-grading the build-up of material to expose the foundation and create a greater clearance.

Additionally, soil and vegetation should not be in contact with the siding or any wood.

Recommendation

Contact a qualified landscaping contractor



Across structure

2.2.5 B. Grading and Drainage

NO GRADING (FLAT) SLOPE



The grading around the structure is relatively level (flat). This may not allow for property water drainage away from the foundation. Ideally, the structure should be the highest point on the property to promote good drainage and water run off away from the structure. Evaluate and address as necessary.

Recommendation

Contact a qualified landscaping contractor





ght Back

2.3.1 C. Roof Covering Materials

Maintenance Item

RE-CAULKING NEEDED

Roof leaks typically occur at penetration points such as roof vents. Re-caulking at these penetration points will help prevent water intrusion. Recommend hiring a contractor to re-caulk with approved roofing caulk and/or silicon sealant as necessary.

Recommendation

Contact a qualified roofing professional.





Merit Property Inspections Page 15 of 40

2.4.1 D. Roof Structures and Attics

INSULATION IS UNEVENLY DISTRIBUTED



Insulation in the attic unevenly distributed and not smooth / even across the attic surface. This is common in older structures where attic insulation has been moved for repairs and installations. Insulation that is not smooth and even across the attic surface will be less efficient and will be unable to create a thermal barrier as intended. Recommend a insulation contractor smooth the insulation and/or install new insulation in areas of the attic, as necessary.

Recommendation

Contact a qualified insulation contractor.







Attic Attic Attic

2.4.2 D. Roof Structures and Attics

ATTIC LADDER DAMAGED



The attic ladder is damaged- Unsafe. Recommend repair of the ladder.

Recommendation

Contact a qualified general contractor.



Garage

2.5.1 E. Walls (Interior and Exterior)

CAULKING DETERIORATED AND/OR MISSING



Caulking is necessary to seal gaps less than 1/2-inch. Calking that is missing can provide for water penetration and allow insect access into the structure.

Recommendation

Contact a qualified general contractor.

Merit Property Inspections Page 16 of 40







Right


2.5.2 E. Walls (Interior and Exterior)

CRACKS MAJOR

Major cracking observed in wall structure that is likely due to structural foundation issues and is considered evidence of a structural deficiency. Recommend a qualified foundation contractor evaluate and advise on course of action.

Recommendation

Contact a foundation contractor.



Garage

2.5.3 E. Walls (Interior and Exterior)

CRACKS MINOR

Minor cracking was observed in wall structure. This is common in structure this age and is often determined to be cosmetic. That said, cracking is a first sign of foundation failure and cracks can grow over time; recommend monitoring.

Recommendation

Recommended DIY Project



2.5.4 E. Walls (Interior and Exterior)

CABINET - ROTTING CABINETRY



One or more areas of the cabinet show signs of rotting wood. This is caused by continual water inundation or active leaking of the plumbing fixtures from above. Recommend replacement of the cabinetry and further evaluation for active moisture issues and signs of mold.

Recommendation

Contact a qualified cabinet contractor.

Merit Property Inspections Page 17 of 40



Primary Bathroom

2.5.5 E. Walls (Interior and Exterior)

THERMAL - HOT/COLD SPOT SHOWING IN THERMAL SCAN

There is a hot or cold spot that is showing in the thermal imagery scan that was performed. This is typically caused by a lack of insulation in the walls. This can also be caused by a settling of blown-in or batt insulation in the walls of older structures. Many of the localized areas in ceilings can be remedied by investigating the insulation areas missing in attic spaces. Wall areas missing insulation can be more difficult to remedy because of access limitations. Some spots may be permanent inefficiencies because of the cost/benefit in trying to remedy the issue. Recommend further investigation by an insulation contractor or an HVAC specialist.

Recommendation

Contact a qualified insulation contractor.







Living

Living

Living

2.5.6 E. Walls (Interior and Exterior) **VEGETATION RUBBING AGAINST** SIDING

Vegetation is rubbing against siding. This may promote moisture and pest intrusion. Recommend a qualified professional trim back

Recommendation

vegetation.

Contact a qualified landscaping contractor



Merit Property Inspections Page 18 of 40

2.6.1 F. Ceilings and Floors


CEILING - SHEETROCK CRACKS MINOR




Minor sheetrock cracking was observed on the ceiling. This is common in structures this age and is often determined to be cosmetic, most often the separation of drywall tape joints. Recommend patching, repainting, monitoring these locations for further cracking.

Recommendation

Contact a qualified painting contractor.





Kitchen Garage

2.6.2 F. Ceilings and Floors

FLOORING - TILES LOOSE / CRACKED OR MISSING



Loose tiles that are popped or missing and/or cracking was observed. This is possibly due to structural foundation issues and is considered evidence of a structural deficiency if on the interior of the structure. Recommend a qualified foundation repair company / contractor evaluate and advise on course of action prior to repair of the flooring.

Recommendation

Contact a qualified flooring contractor



Merit Property Inspections Page 19 of 40

2.6.3 F. Ceilings and Floors

FLOORING - CARPET WRINKLING PRESENT



Carpet wrinkling was present at the time of inspection. Although carpet wrinkling (both in the carpet itself or underlying carpet pad) is generally considered a cosmetic defect, this can indicate structural defects. Additionally carpet wrinkling is considered a safety tripping hazard to pedestrians. Recommend hiring a carpet installer to restretch the carpet and determine the problem.

Recommendation

Contact a qualified flooring contractor



Office

2.6.4 F. Ceilings and Floors

CEILING- EXPOSED NAIL HEADS ON SHEETROCK (NAIL POP)



The sheetrock has nail heads showing (sometimes called "nail pops") where nails have penetrated the mud covering becoming exposed. This is common in homes of this age and is primarily considered a cosmetic deficiency. Often the mud to cover the nail was not thick enough and has "popped off" the sheetrock as the home has aged. It is unlikely that the cause is a structural deficiency. Recommend repaint or hire a general contractor to resolve, as necessary. Monitor area for future nail pops.

Recommendation

Contact a qualified drywall contractor.






Primary Bedroom

Primary Closet

2.7.1 G. Doors (Interior and Exterior)

DOOR RUBS / STICKS AND IS MISALIGNED



Recommendation

Contact a qualified door repair/installation contractor.



2nd Bedroom Closet


Merit Property Inspections Page 20 of 40

2.9.1 H. Windows

SINGLE PANE WINDOWS (ENTIRE PROPERTY)

All (or almost all) windows in the structure appear to be single pane. Single pane windows are less efficient and will lead to higher utility bills. Not all window photos are documented in the section, and photos here should be used as an example. Recommend budgeting for replacement of windows, as necessary, in the future for the entire property to undergo a window replacement.

Note: some historic single pane windows are protected by historical societies. Client should consult relator or the City/County to better areas where window replacements are more difficult.



understand property's that are located within jurisdictional historic

Recommendation

Contact a qualified window repair/installation contractor.

2.9.2 H. Windows

WINDOWS SHOULD BE RECAULKED (ENTIRE PROPERTY)



The entire property has windows that have aged, cracked, and/or missing caulking that should be replaced. Inspector notes noticeable gaps around most/all windows of the property. This can lead to water penetration and insect intrusion. Windows should be recaulked with a silicone based sealant.

Recommendation

Contact a qualified window repair/installation contractor.







Across structure

2.9.3 H. Windows

WINDOW SCREEN IS DAMAGED

Recommendation

Window has a damaged screen. Recommend replacement depending on preference.

Recommendation

Contact a qualified window repair/installation contractor.



Back

Page 21 of 40 Merit Property Inspections

2.11.1 K. Porches, Balconies, Decks, and Carports



OLD CONCRETE - PORCH CRACKS, SEPARATION, OR HEAVING

The porch show signs of aged cracking, separation, heaving, and/or deterioration. This is common in areas of the state that have clay-based soils. Compromised concrete will continue to exhibit decay, failure, collapse, and uplift if not remediated. Recommend caulking larger cracks and applying a concrete sealer. Cracking can also be a safety tripping hazard for pedestrians.

Recommendation

Recommend monitoring.



Merit Property Inspections Page 22 of 40

3: II. ELECTRICAL SYSTEMS

		IN	NI	NP	D
3.1	A. Service Entrance and Panels	Χ			
3.2	B. Branch Circuits, Connected Devices, and Fixtures	Χ			Χ
3.3	C. Low Voltage & Other	Χ			

Information

A. Service Entrance and Panels: Photo(s) of electric meter and service

Overhead Service







A. Service Entrance and Panels: Photo(s) of main electric service panel 200 Amp













Merit Property Inspections Page 23 of 40

A. Service Entrance and Panels: Branch circuit wiring

Copper

Branch wiring (wiring throughout the structure) should be copper for all circuits within structure. Aluminum wire is considered a fire hazard and is caused by oxidation and other factors that lead to overheating where the wire is connected at splices, outlets and light fixtures. Aluminum wire is OK and very common for the main electrical service from the meter.

Limitations

A. Service Entrance and Panels

PIGTAILED WIRES IN PANEL

Pigtailed wires inside the box indicate one of two things. First (1), box may be recently replaced and pigtails are necessary to connect the shorter wires to the new breaker locations. Second (2), wires may be aluminum and pig tailing is necessary to connect the aluminum to the copper only breakers. Inspector is unable to determine if the wires are aluminum or copper throughout the home due to the fact that the pigtail and covers all wire tips.



Garage

Observations

3.2.1 B. Branch Circuits, Connected Devices, and Fixtures



FIXTURE - DAMAGED BULB COVER

Lighting fixture bulb cover is damaged. This is considered a primarily cosmetic deficiency, but can provide some protection for the bulb. Recommend replacement of the bulb cover as necessary.

Recommendation

Contact a qualified electrical contractor.



Front

3.2.2 B. Branch Circuits, Connected Devices, and Fixtures



OUTLET - GFCI NOT FUNCTIONING

GFCI outlet was not functioning properly. This is because it was not tripping or not resetting. Recommend licensed electrician investigating the cause and replacing receptacles that are malfunctioning in all locations necessary.

Recommendation

Contact a qualified electrical contractor.



Hall Bathroom

3.2.3 B. Branch Circuits, Connected Devices, and Fixtures



Merit Property Inspections Page 24 of 40

Recommendation

Contact a qualified electrical contractor.



Garage

4: III. HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS

		IN	NI	NP	D
4.1	A. Heating Equipment	Χ			
4.2	B. Cooling Equipment	Χ			Χ
4.3	C. Duct Systems, Chases, and Vents	Χ			Χ
4.4	D. Other	Χ			

Information

A. Heating Equipment: Photo(s) of 1st heating system

Electric Heat Pump, Age: 0-10 Years



A. Heating Equipment: 1st unit - measured temperature differential

Operable (Not Measured)

B. Cooling Equipment: Exterior - photo(s) of 1st cooling system Electric Central Air Conditioning, R-410A Freon, Age: 0-10 Years





Manufactured 2017

Merit Property Inspections Page 26 of 40

B. Cooling Equipment: Interior - photo(s) of 1st cooling system

Electric Central Air Conditioning, Age: 0-10 Years



Hall Closet Manufactured 2017

B. Cooling Equipment: 1st unit - measured temperature differential Low (0°F to 15°F)



Merit Property Inspections Page 27 of 40

C. Duct Systems, Chases, and Vents: Photo(s) of duct system















Limitations

A. Heating Equipment

HIGH OUTDOOR TEMPERATURE - BRIEF FUNCTIONALITY TEST

The furnace heating system temperature differentials were not able to be measured due to high outdoor temperatures. Operation is considered to be a fire hazard by the inspector. A limited visual inspection was performed and reported. Additionally brief observation of functionality was performed where inspector operates furnace to confirm air handler engagement, fire-like smell, gas/electric draw, and/or active heat. If the client has concerns about the condition of the heating equipment, the inspector recommends hiring a qualified HVAC technician for further evaluation.

A. Heating Equipment

FURNACE-INTERNAL ACCESS PANEL

The furnace access panel (door) was not opened during the inspection. The inspector does not hold an HVAC license and did not inspect the interior components of the furnace. Evaluation of the internal elements (e.g., heat exchanger, burners, electrical connections) is outside the scope of this inspection. Further evaluation by a licensed HVAC professional is recommended if a more comprehensive assessment of the furnace is desired.

B. Cooling Equipment

EVAPORATOR-INTERNAL ACCESS PANEL

Merit Property Inspections Page 28 of 40

The evaporator coil was not inspected beyond general observations of the accessible components. The inspector does not hold an HVAC license and did not open or dismantle the evaporator housing to inspect the internal coil, internal drain pan, or related elements. Detailed inspection of the evaporator coil is outside the scope of this report. Further evaluation by a licensed HVAC professional is recommended if a more thorough assessment is needed.

Observations

4.2.1 B. Cooling Equipment



CONDENSER - FREON INSULATION MISSING OR DAMAGED

Missing or damaged insulation on the refrigerant line can cause energy loss and condensation. Recommend contacting an HVAC professional to replace the missing or damaged insulation.

Recommendation

Contact a qualified HVAC professional.





eft Left

4.2.2 B. Cooling Equipment

Maintenance Item

CONDENSER - VEGETATION IS TOO CLOSE

A tree and/or vegetative growth is too close to the condenser unit. The condenser utilizes the air-space around it to release heat from the structure. Growth around the condenser will lower the efficiency and/or could cause the unit to overheat. Recommend removing or trimming the growth away from the condenser by at least 3-feet on the sides and 10-feet above the unit.

Recommendation

Contact a qualified landscaping contractor





ert Ler

Merit Property Inspections Page 29 of 40

4.2.3 B. Cooling Equipment



EVAPORATOR- FREON LEAK

Freon leak at evaporator. Recommend a qualified professional repair.

Recommendation

Contact a qualified HVAC professional.



Hall Closet

4.3.1 C. Duct Systems, Chases, and Vents



DUCT CLEANING IS RECOMMENDED

Inspector has discovered evidence that the HVAC duct system should be cleaned. This includes either a visual investigation of the plenums through access ports (if available) or supply vents that are dirty, dusty, and/or clogged with debris.

Recommendation

Contact a qualified HVAC professional.



Primary Bathroom

Merit Property Inspections Page 30 of 40

5: IV. PLUMBING SYSTEMS

		IN	NI	NP	D
5.1	A. Plumbing Supply, Distribution Systems, and Fixtures	Χ			Χ
5.2	B. Drains, Wastes, and Vents	Χ			
5.3	C. Water Heating Equipment	Χ			Χ
5.4	D. Hydro-Massage Therapy Equipment	Χ			
5.5	F. Gas Distribution Systems and Gas Appliances			Х	

IN = Inspected NI = Not Inspected NP = Not Present D = Deficiency

Information

A. Plumbing Supply, Distribution Systems, and Fixtures: Photo(s) of water distribution pressure 70-80 psi

This inspection included a water distribution pressure check as part of the inspection package.

The water distribution pressure should range from 40 psi to 80 psi under typical operation. Photos in this section do not represent a pressure deficiency and are for documentation purposes.

Deficiencies from pressure distribution will be documented below and/or throughout the report as discovered.



75 PSI

A. Plumbing Supply, Distribution Systems, and Fixtures: Photo(s) of type of distribution piping materialThroughout the Property

PVC / CPVC

Water distribution piping inside can change underground or in walls, attics, cabinets, or at fixtures. It is common in older structures to see materials types transition to newer materials in areas where repairs have been made. It is impossible to determine if all piping at the property is of the same material type and where all transitions are made. Inspector based his opinions on material type using only visual clues and not using scoping or any other detention method.

CPVC: Chlorinated polyvinyl chloride or CPVC pipe has the strength of PVC but is heat-resistant, which makes it acceptable in many regions for use on interior hot-water supply lines.







Primary Bathroom Kitchen Garage

Merit Property Inspections Page 31 of 40

A. Plumbing Supply, Distribution Systems, and Fixtures: Photo(s) of water shut off location Right of Structure



Right

A. Plumbing Supply, Distribution Systems, and Fixtures: Photo(s) of water meter location Street Left





Front Right

B. Drains, Wastes, and Vents: Photo(s) of type of drain/sewer piping material PVC

Sewer drain piping inside the structure can change underground or in walls, attics, cabinets, or at fixtures. It is common in older structures to see materials types transition to newer materials in areas where repairs have been made. It is impossible to determine if all piping is of the same material type and where all transitions are made. Inspector based his opinions on material type using only visual clues and not using scoping or any other detention method.

PVC: Polyvinyl chloride or PVC is a common sewer plumbing pipe known for its versatility, lightweight, and blockage resistance. PVC piping is generally used as part of a sink, toilet, or shower drain line, though it's sometimes used as a main water supply pipe.





Merit Property Inspections Page 32 of 40

C. Water Heating Equipment: Water heater temperature

Operable (100°F to 130°F)

This inspection included a test of the water heater temperature as part of the inspection package.

Generally accepted safe and comfortable water temperature is one-hundred twenty (120) degrees Fahrenheit from a hot water faucet. A temperature over one-hundred thirty (130) degrees Fahrenheit is general considered to be unsafe.



118°F

C. Water Heating Equipment: Photo(s) of 1st water heater

Electric, Age: 10-15 Years, 40-Gallons







Garage Manufactured 2015

D. Hydro-Massage Therapy Equipment: Photo(s) of hydro-massage








Primary Bathroom

Merit Property Inspections Page 33 of 40

D. Hydro-Massage Therapy Equipment: Photo(s) of GFCI

Hydro massage tubs should have a GFCI trip breaker installed at a receptacle to lower the risk of electrocution. These are commonly located in the master closet or the toilet room at a distance from the tub itself.





Primary Bathroom

Limitations

B. Drains, Wastes, and Vents

SEWER SCOPE IS RECOMMENDED

Inspection of the inside piping of the sewer drain system is not part of the inspection because it is not visible. Although the drain system functionality is briefly tested by running, surging, and draining water at various fixtures, the inspector cannot replicate the same scenarios as the home being lived-in. Clogs, breaks, leaks, and uphill runs can be disguised, particularly in vacant homes, and can manifest/worsen as the property is used. Our inspection does not guarantee that a problem is not present. If the sewer system is 35+ years old, shows any indications of ductile iron pipe being used, if the structure has sat vacant, or if there are any nearby tree roots that could damage the system, then we recommend having a sewer scope inspection to check for cracks, clogs, leaks, breaks or other potentially serious issues with the sewer system.

Observations

5.1.1 A. Plumbing Supply, Distribution Systems, and Fixtures



FIXTURE DRIPPING

A fixture is dripping. Recommend qualified handyman or plumber evaluate and repair.

Recommendation

Contact a qualified plumbing contractor.



Primary Bathroom

5.1.2 A. Plumbing Supply, Distribution Systems, and Fixtures



TOILET IS LOOSE

The toilet is loose at the bolts and is not stable. This may lead to leaks, and it is generally unsafe. Recommend tightening the toilet bolts or hiring a qualified plumbing contractor to tighten and further investigate.

Merit Property Inspections Page 34 of 40

Recommendation

Contact a qualified plumbing contractor.



Primary Bathroom

5.3.1 C. Water Heating Equipment



WATER HEATER SITTING ON THE **GROUND**

The water heater is not elevated off the ground. Water heaters that are sitting on the ground with rust-out faster than elevated water

Recommendation

Contact a qualified plumbing contractor.



Garage

5.3.2 C. Water Heating Equipment

WATER HEATER NEAR OR PAST **EXPECTED SERVICE LIFESPAN**



Typical water heater lifespan is 10-12 years. Water heater is near or past its expected service lifespan. Recommend a qualified professional replace.

Recommendation

Contact a qualified plumbing contractor.



Garage

Merit Property Inspections Page 35 of 40

6: V. APPLIANCES

		IN	NI	NP	D
6.1	A. Dishwashers	Χ			
6.2	B. Food Waste Disposers	Χ			
6.3	C. Range Hood and Exhaust Systems	Χ			
6.4	D. Ranges, Cooktops, and Ovens	Χ			
6.5	E. Microwave Ovens	Χ			
6.6	F. Mechanical Exhaust Vents and Bathroom Heaters	Χ			Χ
6.7	G. Garage Door Operators	Χ			
6.8	H. Dryer Exhaust Systems	Χ			
6.9	I. Refrigerators	Χ			
6.10	J. Washers & Dryers	Χ			

Information

A. Dishwashers: Photo(s) of dishwasher and data tag







Kitchen

B. Food Waste Disposers: Photo(s) of food waste disposer





Kitchen

Merit Property Inspections Page 36 of 40

C. Range Hood and Exhaust Systems: Photo(s) of range/hood exhaust

Recirculating, Microwave Combo





Kitchen

D. Ranges, Cooktops, and Ovens:

Type

Electric

D. Ranges, Cooktops, and Ovens: Photo(s) of range and data tag













E. Microwave Ovens: Photo(s) of microwave and data tag







Merit Property Inspections Page 37 of 40

G. Garage Door Operators: Photo(s) of 1st garage door and/or opener

Automatic







Kitchen

H. Dryer Exhaust Systems: Photo(s) of dryer exhaust system







Laundry

Attic

Left

I. Refrigerators: Photo(s) of refrigerator and data tag





Kitchen

Limitations

I. Refrigerators

OUTSIDE SCOPE - REFRIGERATOR

Inspection of the refrigerator is considered out of the scope of an inspection report because it is often personal property that the seller is often entitled to remove.

These images are considered informational only.

J. Washers & Dryers

OUTSIDE SCOPE - WASHER AND/OR DRYER

Merit Property Inspections Page 38 of 40

Inspection of the washer and/or dryer appliances is considered out of the scope of an inspection report because it is often personal property that the seller is often entitled to remove.

These images are considered informational only.





Laundry

Observations

6.6.1 F. Mechanical Exhaust Vents and Bathroom Heaters

Recommendation

VENT FAN IS NOISY

The vent fan is unusually noisy when powered on. Recommend further investigation to determine the cause of the problem.

Recommendation

Contact a qualified electrical contractor.





Primary Bathroom

Hall Bathroom

7: VII. BROAD LIMITATIONS & CLOSEOUT

IN NI NP D

IN = Inspected

NI = Not Inspected

NP = Not Present

D = Deficiency

Information

Closeout Items

Lights returned to entry status, 1st thermostat returned to entry status, Attic cover returned, Oven is off, Dishwasher is off and drained, Garage doors closed/locked, Exterior door(s) locked, Entry door locked, Key(s) returned

Limitations

System Limitations

ELECTRONICS - OUT OF SCOPE

The functionality of some electronics are not considered part of the inspection scope. These generally include surround sound systems, projectors, internet modems/routers, security systems, computers, servers, etc. Recommend the client have the owner demonstrate the functionality or contacting the manufacturer for a better understanding of the systems.

System Limitations

SWIMMING POOL, SPA, HOT TUB, AND EQUIPMENT - OUT OF SCOPE

The inspection of the pool is outside the scope of this inspection report. Recommend consulting a swimming pool / spa contractor, maintenance provider, or expert to inspect the elements of the system.

System Limitations

SECURITY SYSTEM - OUT OF SCOPE

The functionality of the security system is not considered part of the inspection scope. This generally includes cameras, alarms, control panels, sensors, etc. Recommend the client have the owner demonstrate the functionality or contacting the provider/manufacturer for a better understanding of the system and costs.

Merit Property Inspections Page 40 of 40