4-Point Inspection Form

Insured/Applicant Name:	Buyer Name	Application / Policy #:				
Address Inspected: 1234	Main St , Tampa, FL 33607					
Actual Year Built: 1976		Date Inspected: 06/20/2025				
Minimum Photo Requirements						
☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves						
☑ Main electrical service panel with interior door label						
☑ Electrical box with panel off						
☑ All hazards or deficiencies noted in this report						
A Florida-licensed inspector must complete, sign and date this form.						

Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.

Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.						
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 150 Is amperage sufficient for current usage? ☑ Yes		Second Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 150 Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)				
Indicate presence of any of the following:						
□ Cloth wiring □ Active knob and tube □ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. □ Connections repair via COPALUM crimp □ Connections repair via AlumiConn						
Hazards Present Blowing fuses Tripping breakers Empty sockets Corrosion Loose Wiring Improper grounding Over fusing		□ Double taps □ Exposed wiring □ Unsafe wiring □ Improper breaker size □ Scoring □ Other (explain)				
General condition of the electrical system: ☑ Satisfactory ☐ Unsatisfactory (explain)						
Supplemental information						
Main Panel Second Panel			Wiring Type			
Panel age: Aprx 15 Panel age: Aprx 49			☑ Copper ☑ NM, BX or Conduit			
Year last updated: N/A						
Brand/Model: ITE. Siemens Brand/Model: General E		lectric				

Merit Property Inspections 06/20/2025

Merit Property Inspections Page 1 of 7

4-Point Inspection Form

HVAC System						
Central AC: ✓ Yes ☐ No						
Central heat: ☑ Yes ☐ No						
If not central heat, indicate primary heat source and fuel type:						
Are the heating, ventilation and air conditioning systems in good working or	rder? ☑ Yes ☐ No (explain)					
Date of last HVAC servicing/inspection:						
Hazards Present						
Wood burning stove or central gas fireplace not professionally installed?]Yes ☑No					
Space heater used as primary heat source? ☐ Yes ☑ No						
Is the source portable? ☐ Yes ☑ No						
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?						
Supplemental Information						
Age of system: 2018						
Year last updated: N/A						
(Please attach photo(s) of HVAC equipment, including dated manufacturer's	s plate)					
Plumbing System						
Is there a temperature pressure relief valve on the water heater? 🗹 Yes 🗆	∃No					
Is there any indication of an active leak? \square Yes \bowtie No Is there any indication of a prior leak? \square Yes \bowtie No						
Water bases baseling						
Water neater location: Hall Closet: Manufactured 2023 General condition of the following plumbing fixtures and connections to applicances:						
	1					
Satisfactory Unsatisfactory N/A Dishwasher ☑ □ □	Satisfactory Unsatisfactory N/A Toilets ☑ ☐ ☐					
Refrigerator	Sinks 🗹 🗆					
Washing Machine ☐ ☐	Sump pump □ □ ☑					
Water Heater	Main shut off valve ☐ ☐					
Showers/Tubs	All other visible					
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).						
Supplemental Information						
Age of Piping System:	Type of pipes (check all that apply)					
X_ Original to home	☑ Copper					
Completely re-piped	□ PVC/CPVC					
Partially re-piped	☐ Galvanized					
(Provide year and extent of renovation in the comments below)	□PEX					
N/A	□ Polybutylene					
	☐ Other (specify)					

Merit Property Inspections 06/20/2025

Merit Property Inspections Page 2 of 7

4-Point Inspection Form

Roof (With photos of each roof slo	pe, this section can take the place of	the Roof Inspection Form.)					
Predominant Roof Covering material: Architectural shi Roof age (years): 3 Remaining useful life (years): 17 Date of last roofing permit: 2022-10- Date of last update: If updated (check one):		Secondary Roof Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update: If updated (check one):					
☑ Full Replacement ☐ Partial Replacement % of replacement		☐ Full Replacement ☐ Partial Replacement % of replacement					
Overall condition:		Overall condition:					
☑ Satisfactory ☐ Unsatisfactory (explain below)		☐ Satisfactory ☐ Unsatisfactory (explain below)					
Any visible signs of damage / deter (check all that apply and explain below Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or til Soft spots in decking Visible hail damage Any visible signs of leaks Yes Attic/underside of decking Yes Interior ceilings Yes No	v) es ∄ No	Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks Yes No Attic/underside of decking Yes No Interior ceilings Yes No					
Additional Comments/Observations (use additional pages if needed): All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.							
AL BUK	Certified Professional Inspect	HI16182	2025-06-19				
Inspector Signature Merit Property Inspections Company Name	State & Federal ID Numbers License Type	+8134854335 Work Phone	Date -				

Merit Property Inspections 06/20/2025

Merit Property Inspections Page 3 of 7

4-Point Inspection Form

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Merit Property Inspections Page 4 of 7

Photos, Additional Comments or Observations

Exterior Photos



Electrical System

Panel Photos



HVAC System

HVAC Equipment

Merit Property Inspections Page 5 of 7



Plumbing System


Water Heater




Under cabinet plumbing & drains



Exposed Valves



Roof



Merit Property Inspections Page 7 of 7